

# FIRE ALARM INSPECTION REPORT

**Customer:** Victorian Condo's - Galveston

**Inspection Location:** Victorian Condo's

**Notes:**

**Inspector:** Salvador Vargas, Robert Paxton

**Date:** 10/12/2020 09:00am CDT, 10/13/2020 09:00am CDT

**Job Number:** 19750704

	Level	Device	Address	DESCRIPTION	Pass/Fail	Notes
		1	M33	Manual pull station Garbal dining room	P	
		2	M33	Manual pull station Garball door seven	P	
		3	M33	Manual pull station Garball door five	P	
		4	M33	Manual pull station Garball back door	P	
		5	M33	Smoke photo Garball bathroom	P	
		6	M33	Smoke photo Garball lobby	P	
		7	M33	Smoke photo Garball salon a	P	
		8	M33	Garabaldi salon b smoke photo	P	
		9	M33	Smoke photo garball salon c	P	
		10	M33	Manual pull station tennis court	P	
		11	M33	Smoke photo room 1306	P	
		12	M33	Smoke photo room 1305	P	
		13	M33	Smoke photo room 1304	P	
		14	M33	Smoke photo room 1303	P	
		15	M33	Smoke photo room 1302	P	
		16	M33	Smoke photo room 1206	P	
		17	M33	Smoke photo room 1205	P	
		18	M33	Smoke photo room 1204	P	
		19	M33	Smoke photo room 1203	P	
		20	M33	Smoke photo room 1202	P	
		21	M33	Smoke photo room 1104	P	
		1	M1	Smoke photo room 1103	P	
		2	M1	Smoke photo room 1102	P	
		3	M1	Smoke photo room 1101	P	
		8	M1	Manual pull station 1306	P	
		10	M1	Manual pull station 1206	P	
		17	M1	Manual pull station 1301	P	
		18	M1	Manual pull station 1201	P	
		19	M1	Manual pull station 1104	P	
		20	M1	Manual pull station front desk	P	
		21	M1	Manual pull station 1101	L	
		22	M1	Smoke photo front desk	P	
		23	M1	Smoke photo gift shop	P	
		24	M1	Smoke photo room 1301	P	
		35	M1	Smoke photo room 1201	P	
		36	M1	Smoke photo room 2101	P	
		37	M1	Smoke photo room 2104	P	
		38	M1	Smoke photo room 2204	P	
		39	M1	Manual pull station by 2204	P	
		40	M1	Manual pull station by 2201	P	
		1	M2	Smoke photo room 2102	P	
		2	M2	Smoke photo room 2203	P	
		3	M2	Smoke photo room 2201	P	
		4	M2	Smoke photo room 2303	P	
		5	M2	Smoke photo room 2302	P	
		6	M2	Smoke photo room 2301	P	
		7	M2	Smoke photo room 2304	P	
		8	M2	Smoke photo room 2204	P	
		9	M2	Smoke photo room 2103	P	
		10	M2	Manual pull station 2301	P	
		11	M2	Manual pull station 2304	P	
		1	M3	Smoke photo 3209	P	

# FIRE ALARM INSPECTION REPORT

**Customer:** Victorian Condo's - Galveston

**Inspection Location:** Victorian Condo's

**Notes:**

**Inspector:** Salvador Vargas, Robert Paxton

**Date:** 10/12/2020 09:00am CDT, 10/13/2020 09:00am CDT

**Job Number:** 19750704

	Level	Device	Address	DESCRIPTION	Pass/Fail	Notes
		2	M3	Manual pull station 3125	P	
		3	M3	Smoke photo 3202	P	
		4	M3	Smoke photo 3325	P	
		5	M3	Manual pull station 3101	P	
		6	M3	Manual pull station 3201	P	
		7	M3	Manual pull station 3230	P	
		8	M3	Manual pull station 3330	P	
		9	M3	Manual pull station 3325	P	
		10	M3	Smoke photo 3103	P	
		11	M3	Smoke photo 3117	P	
		12	M3	Smoke photo 3118	F	
		13	M3	Smoke photo 3110	P	
		14	M3	Smoke photo 3112	P	
		15	M3	Smoke photo 3125	P	
		16	M3	Smoke photo 3127	P	
		17	M3	Smoke photo 3128	P	
		18	M3	Smoke photo 3129	P	
		19	M3	Smoke photo 3130	P	
		20	M3	Smoke photo 3227	P	
		21	M3	Smoke photo 3226	P	
		22	M3	Smoke photo 3225	P	
		23	M3	Smoke photo 3223	P	
		24	M3	Smoke photo 3221	P	
		25	M3	Smoke photo 3222	P	
		26	M3	Smoke photo 3210	P	
		27	M3	Smoke photo 3217	P	
		28	M3	Smoke photo 3202	P	
		30	M3	Smoke photo 3214	P	
		36	M3	Smoke photo 3203	P	
		39	M3	Smoke photos 3215	P	
		40	M3	Smoke photo 3206	P	
		41	M3	Smoke photo 3208	P	
		42	M3	Smoke photo 3330	P	
		43	M3	Smoke photo 3309	P	
		44	M3	Smoke photo 3311	P	
		45	M3	Smoke photo 3305	P	
		46	M3	Smoke photo 3201	P	
		47	M3	Smoke photo 3213	P	
		48	M3	Smoke photo 3304	P	
		49	M3	Smoke photo 3221	P	
		50	M3	Smoke photo 3303	P	
		51	M3	Smoke photo 3329	P	
		52	M3	Smoke photo 3328	P	
		53	M3	Smoke photo 3327	P	
		54	M3	Smoke photo 3312	P	
		55	M3	Smoke photo 3322	P	
		56	M3	Smoke photo 3321	P	
		57	M3	Smoke photo 3320	P	
		58	M3	Smoke photo 3308	P	
		59	M3	Smoke photo 3319	P	
		60	M3	Smoke photo 3318	P	
		61	M3	Smoke photo 3306	P	

# FIRE ALARM INSPECTION REPORT

**Customer:** Victorian Condo's - Galveston

**Inspection Location:** Victorian Condo's

**Notes:**

**Inspector:** Salvador Vargas, Robert Paxton

**Date:** 10/12/2020 09:00am CDT, 10/13/2020 09:00am CDT

**Job Number:** 19750704

	Level	Device	Address	DESCRIPTION	Pass/Fail	Notes
		62	M3	Smoke photo 3317	P	
		63		Smoke photo 3315	P	
		64		Smoke photo 3314	P	
		65		Smoke photo 3204	P	
		66		Smoke photo 3205	P	
		67		Smoke photo 3207	P	
		68		Smoke photo 3218	P	
		70		Smoke photo 3212	P	
		71		Smoke photo 3224	P	
		72		Smoke photo 3228	P	
		73		Smoke photo 3229	P	
		74		Smoke photo 3126	P	
		75		Smoke photo 3124	P	
		76		Smoke photo 3123	P	
		77		Smoke photo 3111	P	
		78		Smoke photo 3316	P	
		79		Smoke photo 3122	P	
		80		Smoke photo 3121	P	
		81		Smoke photo 3120	P	
		82		Smoke photo 3119	P	
		83		Smoke photo 3107	P	
		84		Smoke photo 3106	P	Cal maint
		85		Smoke photo 3109	P	
		86		Smoke photo 3105	P	
		87		Smoke photo 3116	P	Cal maint
		88		Smoke photo 3104	P	
		89		Smoke photo 3115	P	
		90		Smoke photo 3114	P	
		91		Smoke photo 3113	P	
		92		Smoke photo 3102	P	
		93		Smoke photo 3101	P	
		94		Smoke photo 3108	P	
		95		Smoke photo 3326	P	
		96		Smoke photo 3216	P	
		97		Smoke photo 3219	P	
		98		Smoke photo 3301	P	
		99		Smoke photo 3323	P	
		100		Smoke photo 3313	P	
		101		Smoke photo 3324	P	
		102		Smoke photo 3319	P	
		103		Smoke photo 3320	P	
		105		Manual pull station 3301	P	
		117		Manual pull station 3130	P	
		118		Manual pull station 3119	P	
		120		Smoke photo building three mechanical room	P	
		125		Manual pull station 3225	P	
		126		Supervisory pump run	P	
		127		Supervisory pump fail	P	
		1	M4	Smoke powder 5302	P	
		2	M4	Smoke photo 5306	P	
		3	M4	Smoke photo 5307	P	
		4	M4	Smoke photo 5309	P	

# FIRE ALARM INSPECTION REPORT

**Customer:** Victorian Condo's - Galveston

**Inspection Location:** Victorian Condo's

**Notes:**

**Inspector:** Salvador Vargas, Robert Paxton

**Date:** 10/12/2020 09:00am CDT, 10/13/2020 09:00am CDT

**Job Number:** 19750704

	Level	Device	Address	DESCRIPTION	Pass/Fail	Notes
		5	M4	Smoke photo 5309	P	
		6	M4	Smoke photo 4304	P	
		7	M4'	Smoke photo 4303	P	Cal maint
		8	M4	Smoke photo 4302	P	
		9	M4	Photo 4207	P	
		10	M4	Smoke photo 4110	P	
		11	M4	Smoke photo 4106	P	
		12	M4	Smoke photo 4105	P	
		13	M4	Smoke photo 4104	F	Missing
		14	M4	Smoke photo 4103	P	
		15	M4	Smoke photo 5201	P	
		16	M4	Smoke photo 5204	P	
		17	M4	Smoke photo 5206	P	
		18	M4	Smoke photo 5109	P	
		19	M4	Smoke photo 5107	P	
		20	M4	Smoke photo 5102	P	
		21	M4	Smoke photo 4101	P	
		22	M4	Manual pull station 5309	P	
		23	M4	Manual pull station 4310	P	
		24	M4	Manual pull station 4306	P	
		25	M4	Manual pull station 4301	P	
		26	M4	Manual pull station 5209	P	
		27	M4	Manual pull station 4210	P	
		28	M4	Manual pull station 4206	P	
		29	M4	Manual pull station 4201	P	
		30	M4	Manual pull station 5109	P	
		31	M4	Manual pull station 4110	P	
		32	M4	Manual pull station 4106	P	
		33	M4	Manual pull station 4101	P	
		34	M4	Manual pull station 4108	P	
		35	M4	Manual pull station 4109	P	
		36	M4	Smoke photo 4202	P	
		37	M4	Smoke photo 4292	P	
		38	M4	Smoke photo 4205	P	
		39	M4	Smoke photo 4206	P	
		40	M4	Smoke photo 4208	P	
		41	M4	Smoke photo 4209	P	
		42	M4	Smoke photo 4210	P	
		43	M4	Smoke photo 4305	P	Cal maint
		44	M4	Smoke photo 4306	P	
		45	M4	Smoke photo 4308	P	
		46	M4	Smoke photo 5101	P	
		47	M4	Smoke photo 5103	P	
		48	M4	Smoke photo 5108	P	
		49	M4	Smoke photo 5202	P	
		50	M4	Smoke photo 5205	P	
		51	M4	Smoke photo 5207	P	
		52	M4	Smoke photo 5208	P	
		53	M4	Smoke photo 5209	P	
		54	M4	Smoke photo 5303	P	
		55	M4	Smoke photo 5304	P	
		56	M4	Smoke photo 5308	P	

# FIRE ALARM INSPECTION REPORT

**Customer:** Victorian Condo's - Galveston

Inspection Location: Victorian Condo's

Notes:

Inspector: Salvador Vargas, Robert Paxton

**Date:** 10/12/2020 09:00am CDT, 10/13/2020 09:00am CDT

Job Number: 19750704

[illegible]

# FIRE ALARM INSPECTION REPORT

**Customer:** Victorian Condo's - Galveston

Inspection Location: Victorian Condo's

Notes:

Inspector: Salvador Vargas, Robert Paxton

**Date:** 10/12/2020 09:00am CDT, 10/13/2020 09:00am CDT

Job Number: 19750704

[illegible]

# FIRE ALARM INSPECTION REPORT

**Customer:** Victorian Condo's - Galveston

Inspection Location: Victorian Condo's

Notes:

Inspector: Salvador Vargas, Robert Paxton

**Date:** 10/12/2020 09:00am CDT, 10/13/2020 09:00am CDT

Job Number: 19750704

[illegible]

# FIRE ALARM INSPECTION REPORT

**Customer:** Victorian Condo's - Galveston

Inspection Location: Victorian Condo's

Notes:

Inspector: Salvador Vargas, Robert Paxton

**Date:** 10/12/2020 09:00am CDT, 10/13/2020 09:00am CDT

Job Number: 19750704

[illegible]



# FIRE ALARM INSPECTION REPORT

**Customer:** Victorian Condo's - Galveston

Inspection Location: Victorian Condo's

Notes:

Inspector: Salvador Vargas, Robert Paxton

**Date:** 10/12/2020 09:00am CDT, 10/13/2020 09:00am CDT

Job Number: 19750704

[illegible]

# FIRE ALARM INSPECTION REPORT

**Customer:** Victorian Condo's - Galveston

Inspection Location: Victorian Condo's

Notes:

Inspector: Salvador Vargas, Robert Paxton

**Date:** 10/12/2020 09:00am CDT, 10/13/2020 09:00am CDT

Job Number: 19750704

[illegible]