

FIRE ALARM INSPECTION REPORT

Customer: Victorian Condo's - Galveston

Inspection Location: Victorian Condo's

Notes:

Inspector: Salvador Vargas, Robert Paxton

Date: 10/12/2020 09:00am CDT, 10/13/2020 09:00am CDT

Job Number: 19750704

	Level	Device	Address	DESCRIPTION	Pass/Fail	Notes
			M4	Smoke photo 4201		
				Smoke photo 4102		
				Smoke photo 4107		
				Smoke photo 4204		
				Smoke photo 4307		
				Smoke photo 5104		
				Smoke photo 5105		
				Smoke photo 5305		
				Smoke photo 4310		
			M4	Smoke photo 4301		
			M5	Smoke photo 6101		Cal trouble
				Smoke photo 6103		
				Smoke photo 6105		
				Smoke photo 6106		
				Smoke photo 6109		
				Smoke photo 6110		
				Smoke photo 6206		
				Smoke photo 6207		
				Smoke photo 6208		
				Smoke photo 6209		
				Smoke photo 6210		
				Smoke photo 6301		
				Smoke photo 6302		
				Smoke photo 6303		
				Smoke photo 6307		
				Smoke photo 6310		
				Manual pull station 6106		
				Manual pull station 6110		
				Manual pull station 6210		
				Manual pull station 6206		
				Manual pull station 6201		
				Manual pull station 6301		
				Manual pull station 6306		
				Manual pull station 6310		
				Smoke photo EL ISS a Port room		
				Smoke photo by ELISS a toilet		
				Smoke photo by ELISSA Lonestar room		
				Smoke photo Lonestar room		
				Smoke photo accounting second floor		
				Smoke photo accounting second floor		
				Smoke photo Alyssa starboard		
				Smoke photo storage by 6301		
				Smoke photo storage by 5201		
				Smoke photo room 6102		
				Smoke photo 6104		
				Smoke photo 6108		
				Smoke photo 6201		
				Smoke photo 6202		
				Smoke photo 6203		
				Smoke photo 6204		
				Smoke photo 6205		
			M5	Smoke photo 6305		

FIRE ALARM INSPECTION REPORT

Customer: Victorian Condo's - Galveston

Inspection Location: Victorian Condo's

Notes:

Inspector: Salvador Vargas, Robert Paxton

Date: 10/12/2020 09:00am CDT, 10/13/2020 09:00am CDT

Job Number: 19750704

	Level	Device	Address	DESCRIPTION	Pass/Fail	Notes
			M5	Smoke photo 6306		
				Smoke photo 6308		
			M5	Smoke photo 6309		
			M6	Smoke photo 8102		
				Smoke photo 8104		
				Smoke photo 8203		
				Smoke photo 8204		
				Smoke photo 8301		
				Smoker photo 8303		
				Smoke photo 7101		
				Smoke photo 7102		
				Smoke photo 7104		
				Photo 7105		
				Smoke photo 7106		
				Smoke photo 7107		
				Smoke photo 7108		
				Smoke photo 7109		
				Photo 7201		
				Smoke photos 7203		
				Smoke photo 7209		
				Smoke photo 7302		
				Smoke photo 7304		
				Smoke photo 7306		
				Smoke photo 7307		
				Manual pull station 7109		
				Smoke photo 8201		
				Smoke photo 8202		
				Manual pull station 7201		
				Smoke photo 8103		
				Smoke photo 8101		
				Manual pull station 7309		
				Smoke photo 7301		
				Manual pull station 8101		
				Manual pull station 8104		
				Manual pull station 7202		
				Smoke photo 7202		
				Smoke photo 7205		
				Smoke photo 7206		
				Smoke photo 7208		
				Smoke photo 7303		
				Smoke photo 7305		
				Smoke photo 7308		
				Smoke photo 7309		
				Manual pull station 8301		
				Manual Pull station 8304		
				Smoke photo 8304		
				Manual pull station 8201		
			M6	Manual pull station 8204		
			M7	Manual pull station 9329		
				Manual pull station 9125		
				Smoke photo 9330 office		
			M7	Smoke photo 9311		

FIRE ALARM INSPECTION REPORT

Customer: Victorian Condo's - Galveston

Inspection Location: Victorian Condo's

Notes:

Inspector: Salvador Vargas, Robert Paxton

Date: 10/12/2020 09:00am CDT, 10/13/2020 09:00am CDT

Job Number: 19750704

	Level	Device	Address	DESCRIPTION	Pass/Fail	Notes
			M7	Smoke photo 9114		
				Smoke photo 9103		
				Smoke photo 9118		
				Smoke photo 9107		
				Smoke photo 9108		
				Smoke photo 9120		
				Smoke photo 9109		
				Smoke photo 9110		
				Smoke photo 9111		
				Smoke photo 9126		
				Smoke photo 91 24		
				Smoke photo 9121		
				Smoke photo 9122		
				Smoke photo 9224		
				Smoke photo 9215		
				Smoke photo 9209		
				Smoke photo 9220		
				Smoke photo 9210		
				Smoke follow 9211		
				Smoke photo9223		
				Smoke photo 9228		
				Smoke photo 9328		
				Smoke photo 9304		
				Smoke photo 9303		
				Smoke photo 9315		
				Smoke photo 9302		
				Smoke photo 9207		
				Smoke photo 9301		
				Smoke photo 9313		
				Smoke photo 9316		
				Smoke photo 9308		
				Smoke photo 93 29		
				Smoke photo 9202		
				Smoke photo 9214		
				Smoke photo 9204		
				Smoke photo 9123		
				Smoke photo 9117		
				Smoke photo 9317		
				Smoke photo 9306		
				Smoke photo 9319		
				Smoke photo 9320		
				Smoke photo 93 24		
				Smoke photo 9227		
				Smoke photo 9327		
				Smoke photo 9312		
				Smoke photo 91 29		
				Smoke photo 9216		
				Smoke photo 9222		
				Smoke photo 9225		
				Smoke photo 9305		
				Manual pull station 9325		
			M7	Manual pull station 9306		

FIRE ALARM INSPECTION REPORT

Customer: Victorian Condo's - Galveston

Inspection Location: Victorian Condo's

Notes:

Inspector: Salvador Vargas, Robert Paxton

Date: 10/12/2020 09:00am CDT, 10/13/2020 09:00am CDT

Job Number: 19750704

[illegible]

FIRE ALARM INSPECTION REPORT

Customer: Victorian Condo's - Galveston

Inspection Location: Victorian Condo's

Notes:

Inspector: Salvador Vargas, Robert Paxton

Date: 10/12/2020 09:00am CDT, 10/13/2020 09:00am CDT

Job Number: 19750704

[illegible]

FIRE ALARM INSPECTION REPORT

Customer: Victorian Condo's - Galveston

Inspection Location: Victorian Condo's

Notes:

Inspector: Salvador Vargas, Robert Paxton

Date: 10/12/2020 09:00am CDT, 10/13/2020 09:00am CDT

Job Number: 19750704

[illegible]

FIRE ALARM INSPECTION REPORT

Customer: Victorian Condo's - Galveston

Inspection Location: Victorian Condo's

Notes:

Inspector: Salvador Vargas, Robert Paxton

Date: 10/12/2020 09:00am CDT, 10/13/2020 09:00am CDT

Job Number: 19750704

[illegible]

FIRE ALARM INSPECTION REPORT

Customer: Victorian Condo's - Galveston

Inspection Location: Victorian Condo's

Notes:

Inspector: Salvador Vargas, Robert Paxton

Date: 10/12/2020 09:00am CDT, 10/13/2020 09:00am CDT

Job Number: 19750704

[illegible]

FIRE ALARM INSPECTION REPORT

Customer: Victorian Condo's - Galveston

Inspection Location: Victorian Condo's

Notes:

Inspector: Salvador Vargas, Robert Paxton

Date: 10/12/2020 09:00am CDT, 10/13/2020 09:00am CDT

Job Number: 19750704

[illegible]

FIRE ALARM INSPECTION REPORT

Customer: Victorian Condo's - Galveston

Inspection Location: Victorian Condo's

Notes:

Inspector: Salvador Vargas, Robert Paxton

Date: 10/12/2020 09:00am CDT, 10/13/2020 09:00am CDT

Job Number: 19750704

[illegible]



Island Fire & Safety Equipment Co., Inc.

d.b.a. A-1 FIRE EQUIPMENT COMPANY

3202 Main Street

La Marque, TX 77568

(409) 744-4438 Fax (409) 938-1331

ACR 1750774 ECR 973 SCR-G-1847307

Owner Name: Victorian Condo's - Galveston

Owner Address: 6300 Seawall Blvd.

Galveston

Building Address: 6300 Seawall Blvd.

Galveston

Date of Inspection: 10/12/2020 09:00am CDT, 10/13/2020 09:00am CDT

Name of Inspector: Salvador Vargas, Robert Paxton

Inspection Report

Weekly Pump House / Pump Room

Monthly Pump- Electric

Pump House / Pump Room Inspection

1. Pump House / Room at least 40 F? _____
2. Fire Pump indicating power lights on? _____
3. Transfer Switch in normal situation? _____
4. Phase reversal indicating normal? _____
5. Water storage tank level at? _____
6. Oil level in right angle gear drive? _____
7. All drains working properly? _____
8. All guards and covers installed? _____

Additional Notes:

Electric Fire Pump

1. Did the pump start automatically? _____
Starting Pressure _____psi
2. Did the pump run for at least 10 minutes? _____
Suction _____psi Discharge _____psi
3. Are packing glands leaking? (Adjust if necessary) _____
4. Is the pump free from unusual noise or vibration? _____
5. Are packing boxes, bearings, or
pump casings overheating? _____
6. Is the casing relief valve working? _____

Additional Notes:

Diesel Fire Pump

1. Record engine run timer reading _____
2. Is fuel tank at least 3/4 full? _____
3. Battery voltage and reading #1 _____
_____ 12V _____ 24V #2 _____
4. Low Battery Alarm on or off? _____
5. Are Battery terminals free from corrosion? _____
6. Is control switch in auto position? _____
7. Is the crank case oil level normal? _____
8. Is the electrolyte level in the battery correct? _____
9. Is the cooling water level with antifreeze? _____
10. Is the water jacket heater operating? _____
11. Did the pump start automatically? _____
Starting pressure _____psi
12. Did the pump run for at least 30 min? _____
Suction _____psi Discharge _____psi
13. Is the relief valve on the diesel working? _____
14. Is the relief valve on the pump working? _____
15. Are the packing glands leaking? (Adjust if necessary) _____
16. Record engine RPM _____
17. Is the engine oil pressure gauge working? _____
18. Is the engine temperature normal? _____
19. Is the pump free from unusual noise or vibration? _____
20. Is the a manual stop on both battery banks? _____
Bank #1 _____ Bank #2 _____



Island Fire & Safety Equipment Co., Inc.

d.b.a. A-1 FIRE EQUIPMENT COMPANY

3202 Main Street

La Marque, TX 77568

(409) 744-4438 Fax (409) 938-1331

ACR 1750774 ECR 973 SCR-G-1847307

Owner Name: Victorian Condo's - Galveston

Owner Address: 6300 Seawall Blvd.

Galveston

Building Address: 6300 Seawall Blvd.

Galveston

Date of Inspection: 10/12/2020 09:00am CDT, 10/13/2020 09:00am CDT

Name of Inspector: Salvador Vargas, Robert Paxton

Inspection Report

Weekly Pump House / Pump Room

Monthly Pump- Electric

Pump House / Pump Room Inspection

1. Pump House / Room at least 40 F? _____
2. Fire Pump indicating power lights on? _____
3. Transfer Switch in normal situation? _____
4. Phase reversal indicating normal? _____
5. Water storage tank level at? _____
6. Oil level in right angle gear drive? _____
7. All drains working properly? _____
8. All guards and covers installed? _____

Additional Notes:

Electric Fire Pump

1. Did the pump start automatically? _____
Starting Pressure _____psi
2. Did the pump run for at least 10 minutes? _____
Suction _____psi Discharge _____psi
3. Are packing glands leaking? (Adjust if necessary) _____
4. Is the pump free from unusual noise or vibration? _____
5. Are packing boxes, bearings, or
pump casings overheating? _____
6. Is the casing relief valve working? _____

Additional Notes:

Diesel Fire Pump

1. Record engine run timer reading _____
2. Is fuel tank at least 3/4 full? _____
3. Battery voltage and reading _____ #1 _____
_____ 12V _____ 24V #2 _____
4. Low Battery Alarm on or off? _____
5. Are Battery terminals free from corrosion? _____
6. Is control switch in auto position? _____
7. Is the crank case oil level normal? _____
8. Is the electrolyte level in the battery correct? _____
9. Is the cooling water level with antifreeze? _____
10. Is the water jacket heater operating? _____
11. Did the pump start automatically? _____
Starting pressure _____psi
12. Did the pump run for at least 30 min? _____
Suction _____psi Discharge _____psi
13. Is the relief valve on the diesel working? _____
14. Is the relief valve on the pump working? _____
15. Are the packing glands leaking? (Adjust if necessary) _____
16. Record engine RPM _____
17. Is the engine oil pressure gauge working? _____
18. Is the engine temperature normal? _____
19. Is the pump free from unusual noise or vibration? _____
20. Is the a manual stop on both battery banks? _____
Bank #1 _____ Bank #2 _____