

DETECTOR STATUS

Account 9219: uploaded on 12/6/2025 12:21:13 PM

Legend:

- Sen:** Lists the smoke sensitivity in percent per foot obscuration or degrees F. which will cause an alarm.
- ATL:** Alarm Threshold. Analog value at which a sensor will indicate an alarm condition.
- ACA:** Average Clear Air. Same as the CAV except averaged and filtered over time.
- MT:** Maintenance Threshold. Analog value at which a point is in need of inspection or maintenance.
- TT:** Trouble Threshold. Analog value at which a point indicate a trouble condition.
- CAV:** Current Analog Value. Instantaneous analog value of the sensor.
- CA%:** Current Percent Alarm. Indicates how close the analog value is to alarm.
- PCA/CO:** Peak Clear Air. Indicates the highest analog value (CO in ppm) for the sensor.
- PA%:** Peak Percent Alarm. Same as the CA% except how close the peak value is to alarm.
- Status:** Normal: Detector requires no maintenance.
Cal Maint: Cleaning recommended. Detector is close to noncompliance.
Cal Trouble: Detector is not in compliance with NFPA 72 - needs cleaning, etc.
- NFPA72:** Yes means that the detector is within compliance of NFPA 72 requirements for a detector operating within its marked and listed sensitivity range.
No means it is not in compliance.

ID	Name	Type	Zn	Sen	ATL	ACA	MT	TT	CAV	CA%	PCA/CO	PA%	Status	NFPA72
03:001	dining room 3rd fl	Photo	1	1.5	145	83	113	120	83	0	84	1	Normal	Yes
03:002	dining room 3rd fl	Photo	1	1.5	142	80	113	120	80	0	82	3	Normal	Yes
03:003	hall by dining 3rd	Photo	1	1.5	143	80	113	120	79	0	83	4	Normal	Yes
03:004	room 303	Photo	1	1.5	142	80	113	120	80	0	85	8	Normal	Yes
03:005	hall by 303	Photo	1	1.5	147	85	113	120	85	0	87	3	Normal	Yes
03:006	room 306	Photo	1	1.5	136	74	113	120	74	0	76	3	Normal	Yes
03:007	room 305	Photo	1	1.5	143	80	113	120	81	1	84	6	Normal	Yes
03:008	room 308	Photo	1	1.5	146	84	113	120	84	0	85	1	Normal	Yes
03:009	room 307	Photo	1	1.5	145	83	113	120	83	0	85	3	Normal	Yes
03:010	hall by 307	Photo	1	1.5	148	86	113	120	86	0	88	3	Normal	Yes
03:011	room 310	Photo	1	1.5	144	82	113	120	83	1	84	3	Normal	Yes
03:012	room 309	Photo	1	1.5	140	77	113	120	79	3	79	3	Normal	Yes
03:013	room 312	Photo	1	1.5	147	85	113	120	85	0	86	1	Normal	Yes
03:014	small elev. 3rd fl.	Photo	6	1.5	146	84	113	120	83	0	85	1	Normal	Yes
03:015	by living room 3rd	Photo	1	1.5	149	87	113	120	87	0	89	3	Normal	Yes
03:016	room 314	Photo	1	1.5	143	80	113	120	80	0	85	7	Normal	Yes
03:017	living room 3rd fl	Photo	1	1.5	146	84	113	120	84	0	87	4	Normal	Yes
03:018	library 3rd fl	Photo	1	1.5	150	88	113	120	89	1	91	4	Normal	Yes
03:019	3rd fl big elev.	Photo	3	1.5	149	87	113	120	87	0	90	4	Normal	Yes
03:020	room 320	Photo	1	1.5	145	83	113	120	83	0	84	1	Normal	Yes
03:021	room 321	Photo	1	1.5	148	86	113	120	86	0	89	4	Normal	Yes
03:022	room 322	Photo	1	1.5	144	81	113	120	81	0	83	3	Normal	Yes
03:023	hall by room 322	Photo	1	1.5	145	83	113	120	83	0	86	4	Normal	Yes
03:024	room 323	Photo	1	1.5	151	90	113	120	89	0	92	3	Normal	Yes
03:025	room 324	Photo	1	1.5	147	86	113	120	85	0	88	3	Normal	Yes
03:026	room 325	Photo	1	1.5	141	79	113	120	79	0	81	3	Normal	Yes
03:027	room 326	Photo	1	1.5	153	91	113	120	92	1	93	3	Normal	Yes
03:028	hall by room 326	Photo	1	1.5	152	90	113	120	90	0	97	11	Normal	Yes
03:029	room 327	Photo	1	1.5	156	95	113	120	95	0	103	13	Normal	Yes
03:030	room 328	Photo	1	1.5	144	82	113	120	83	1	87	8	Normal	Yes
03:031	room 329	Photo	1	1.5	145	83	113	120	83	0	104	33	Normal	Yes
03:032	room 330	Photo	1	1.5	145	83	113	120	84	1	85	3	Normal	Yes
03:033	hall by rm 330	Photo	1	1.5	146	84	113	120	84	0	88	6	Normal	Yes
03:034	room 331	Photo	1	1.5	137	75	113	120	75	0	78	4	Normal	Yes
03:035	room 332	Photo	1	1.5	147	86	113	120	85	0	92	9	Normal	Yes
03:036	room 333	Photo	1	1.5	148	86	113	120	86	0	88	3	Normal	Yes
03:037	room 334	Photo	1	1.5	145	83	113	120	83	0	87	6	Normal	Yes
03:038	hall by room 334	Photo	1	1.5	140	78	113	120	77	0	81	4	Normal	Yes
03:039	room 335	Photo	1	1.5	145	83	113	120	84	1	85	3	Normal	Yes
03:040	activity room 3rd fl	Photo	1	1.5	145	83	113	120	83	0	87	6	Normal	Yes
03:041	room 301	Photo	1	1.5	152	89	113	120	90	1	94	7	Normal	Yes
03:042	soiled utility 3rd fl	Photo	1	1.5	146	84	113	120	83	0	87	4	Normal	Yes

DETECTOR STATUS

ID	Name	Type	Zn	Sen	ATL	ACA	MT	TT	CAV	CA%	PCA/CO	PA%	Status	NFPA72
03:043	clean utility 3rd fl	Photo	1	1.5	144	82	113	120	82	0	85	4	Normal	Yes
03:044	staff lockers 3rd fl	Photo	1	1.5	122	60	113	120	60	0	61	1	Normal	Yes
03:045	med. closet 3rd fl	Photo	1	1.5	143	81	113	120	82	1	83	3	Normal	Yes
03:046	nurses station 3rd f	Photo	1	1.5	164	102	113	120	101	0	108	9	Normal	Yes
03:047	3rd fl storage	Photo	1	1.5	142	80	113	120	81	1	83	4	Normal	Yes
03:048	3rd fl warming kitc.	Heat	1	135	135	0	N/A	N/A	82	60	95	70	Normal	Yes
03:049	elev mech rm big	Photo	2	1.5	155	93	113	120	93	0	98	8	Normal	Yes
03:050	elev mech small	Photo	5	1.5	140	77	113	120	77	0	81	6	Normal	Yes
03:051	big elev top shaft	Photo	3	1.5	147	85	113	120	84	0	88	4	Normal	Yes
03:052	big elev top shaft	Heat	9	135	135	0	N/A	N/A	71	52	75	55	Normal	Yes
03:053	small elev top shaft	Photo	6	1.5	147	85	113	120	84	0	89	6	Normal	Yes
03:054	small elev top shaft	Heat	10	135	135	0	N/A	N/A	71	52	73	54	Normal	Yes
03:070	3rd fl closet by act	Heat	1	135	135	0	N/A	N/A	68	50	75	55	Normal	Yes
03:071	hall by rm 325	Photo	1	1.5	147	84	113	120	84	0	88	6	Normal	Yes
03:099	3RD FL MECH RM	Photo	1	1.5	0	91	113	120	0	-1	0	-1	Normal	Yes
06:001	dining room 2nd	Photo	1	1.5	146	85	113	120	85	0	89	6	Normal	Yes
06:002	dining room 2nd fl	Photo	1	1.5	140	78	113	120	79	1	80	3	Normal	Yes
06:003	hall by rm 201	Photo	1	1.5	150	89	113	120	88	0	93	6	Normal	Yes
06:004	room 203	Photo	1	1.5	147	85	113	120	85	0	89	6	Normal	Yes
06:005	hall by rm 205	Photo	1	1.5	143	81	113	120	82	1	84	4	Normal	Yes
06:006	room 206	Photo	1	1.5	144	82	113	120	82	0	84	3	Normal	Yes
06:007	room 205	Photo	1	1.5	141	79	113	120	79	0	100	33	Normal	Yes
06:008	room 208	Photo	1	1.5	122	60	113	120	60	0	60	0	Normal	Yes
06:009	room 207	Photo	1	1.5	144	83	113	120	81	0	85	3	Normal	Yes
06:010	hall by rm 209	Photo	1	1.5	152	90	113	120	90	0	93	4	Normal	Yes
06:011	room 210	Photo	1	1.5	141	78	113	120	79	1	96	28	Normal	Yes
06:012	room 209	Photo	1	1.5	142	81	113	120	80	0	93	19	Normal	Yes
06:013	room 212	Photo	1	1.5	140	78	113	120	77	0	81	4	Normal	Yes
06:014	2nd fl small elev.	Photo	6	1.5	145	83	113	120	83	0	86	4	Normal	Yes
06:015	by living area 2nd	Photo	1	1.5	154	92	113	120	91	0	95	4	Normal	Yes
06:016	room 214	Photo	1	1.5	146	84	113	120	83	0	86	3	Normal	Yes
06:017	2nd fl living room	Photo	1	1.5	143	81	113	120	80	0	84	4	Normal	Yes
06:018	2nd fl library	Photo	1	1.5	144	83	113	120	83	0	86	4	Normal	Yes
06:019	2nd fl big elev.	Photo	3	1.5	156	95	113	120	94	0	98	4	Normal	Yes
06:020	rm 220	Photo	1	1.5	150	88	113	120	88	0	125	59	Normal	Yes
06:021	rm 221	Photo	1	1.5	143	82	113	120	83	1	94	19	Normal	Yes
06:022	rm 222	Photo	1	1.5	143	81	113	120	82	1	87	9	Normal	Yes
06:023	rm 223	Photo	1	1.5	140	78	113	120	78	0	85	11	Normal	Yes
06:024	hall by 223	Photo	1	1.5	150	88	113	120	88	0	91	4	Normal	Yes
06:025	rm 224	Photo	1	1.5	150	87	113	120	88	1	253	263	Normal	Yes
06:026	rm 225	Photo	1	1.5	148	86	113	120	87	1	96	16	Normal	Yes
06:027	rm 226	Photo	1	1.5	150	87	113	120	87	0	94	11	Normal	Yes
06:028	hall by rm 227	Photo	1	1.5	146	84	113	120	85	1	88	6	Normal	Yes
06:029	rm 227	Photo	1	1.5	150	88	113	120	88	0	91	4	Normal	Yes
06:030	rm 228	Photo	1	1.5	146	84	113	120	84	0	91	11	Normal	Yes
06:031	rm 229	Photo	1	1.5	122	60	113	120	60	0	61	1	Normal	Yes
06:032	rm 230	Photo	1	1.5	146	84	113	120	84	0	102	29	Normal	Yes
06:033	hall by rm 231	Photo	1	1.5	135	72	113	120	74	3	76	6	Normal	Yes
06:034	rm 231	Photo	1	1.5	150	88	113	120	89	1	91	4	Normal	Yes
06:035	rm 232	Photo	1	1.5	122	60	113	120	60	0	60	0	Normal	Yes
06:036	rm 233	Photo	1	1.5	145	83	113	120	83	0	97	22	Normal	Yes
06:037	rm 234	Photo	1	1.5	122	60	113	120	60	0	61	1	Normal	Yes
06:038	hall by rm 235	Photo	1	1.5	141	78	113	120	79	1	82	6	Normal	Yes
06:039	rm 235	Photo	1	1.5	151	89	113	120	89	0	92	4	Normal	Yes
06:040	activity area 2nd	Photo	1	1.5	140	79	113	120	78	0	82	4	Normal	Yes
06:041	room 201	Photo	1	1.5	146	84	113	120	84	0	88	6	Normal	Yes
06:042	soiled utility 2nd	Photo	1	1.5	152	90	113	120	89	0	92	3	Normal	Yes
06:043	clean utility 2nd	Photo	1	1.5	144	82	113	120	82	0	85	4	Normal	Yes
06:044	staff locker 2nd	Photo	1	1.5	152	90	113	120	90	0	93	4	Normal	Yes
06:045	med rm. 2nd	Photo	1	1.5	140	78	113	120	78	0	82	6	Normal	Yes
06:046	nurses station 2nd	Photo	1	1.5	152	90	113	120	91	1	98	12	Normal	Yes

DETECTOR STATUS

ID	Name	Type	Zn	Sen	ATL	ACA	MT	TT	CAV	CA%	PCA/CO	PA%	Status	NFPA72
06:047	storage 2nd	Photo	1	1.5	145	83	113	120	84	1	86	4	Normal	Yes
06:048	kitchen 2nd fl	Heat	1	135	135	0	N/A	N/A	78	57	91	67	Normal	Yes
06:049	dining room 2nd	Photo	1	1.5	146	84	113	120	84	0	87	4	Normal	Yes
06:050	2nd fl storage stair	Heat	1	135	135	0	N/A	N/A	71	52	75	55	Normal	Yes
06:080	rah #8 2nd fl	Photo Duct	1	1.1	123	61	113	120	60	0	89	45	Normal	Yes
06:081	hwah #7 2nd fl	Photo Duct	1	1.1	115	53	113	120	53	0	55	3	Normal	Yes
06:098	2nd fl activity rm	Photo	1	1.5	146	83	113	120	83	0	89	9	Normal	Yes
06:099	2nd fl mech room	Photo	1	1.5	0	60	113	120	0	-1	0	-1	Normal	Yes
09:001	alt. conference room	Photo	1	1.5	122	60	113	120	59	0	70	16	Normal	Yes
09:002	rm 126	Photo	1	1.5	144	81	113	120	82	1	84	4	Normal	Yes
09:003	rm 124	Photo	1	1.5	148	86	113	120	86	0	88	3	Normal	Yes
09:004	rm 122	Photo	1	1.5	153	90	113	120	90	0	93	4	Normal	Yes
09:005	rm 120	Photo	1	1.5	149	87	113	120	87	0	90	4	Normal	Yes
09:006	rm 118	Photo	1	1.5	113	51	113	120	50	0	56	8	Normal	Yes
09:007	rm 116	Photo	1	1.5	146	83	113	120	84	1	88	7	Normal	Yes
09:008	rm 114	Photo	1	1.5	122	60	113	120	60	0	63	4	Normal	Yes
09:009	rm 112	Photo	1	1.5	122	60	113	120	60	0	68	12	Normal	Yes
09:010	rm 110	Photo	1	1.5	148	86	113	120	85	0	103	27	Normal	Yes
09:011	rm 108	Photo	1	1.5	122	60	113	120	60	0	62	3	Normal	Yes
09:012	dining rm alt	Heat	1	135	135	0	N/A	N/A	62	45	89	65	Normal	Yes
09:013	dining rm alt.	Photo	1	1.5	122	60	113	120	60	0	62	3	Normal	Yes
09:014	hall by rm 112	High-HT	1	150	150	0	N/A	N/A	60	40	80	53	Normal	Yes
09:015	hall by rm 116	Heat	1	135	135	0	N/A	N/A	60	44	82	60	Normal	Yes
09:016	hall by rm 120	Photo	1	1.5	122	60	113	120	60	0	62	3	Normal	Yes
09:017	hall by rm 124	Photo	1	1.5	178	117	113	120	116	0	123	9	Cal Mainte	Yes
09:018	hall by rm 121	Photo	1	1.5	155	93	113	120	92	0	100	11	Normal	Yes
09:019	rm 121	Photo	1	1.5	122	60	113	120	60	0	64	6	Normal	Yes
09:020	rm 119	Photo	1	1.5	122	60	113	120	60	0	61	1	Normal	Yes
09:021	rm 117	Photo	1	1.5	158	96	113	120	95	0	99	4	Normal	Yes
09:022	rm 115	Photo	1	1.5	149	87	113	120	87	0	91	6	Normal	Yes
09:023	beauty salon	Photo	1	1.5	145	83	113	120	84	1	88	8	Normal	Yes
09:024	oxygen room	Photo	1	1.5	122	60	113	120	60	0	62	3	Normal	Yes
09:025	activities	Photo	1	1.5	122	60	113	120	60	0	61	1	Normal	Yes
09:027	hall by kitchen	Heat	1	135	135	0	N/A	N/A	64	47	86	63	Normal	Yes
09:028	hall by rm 111	Heat	1	135	135	0	N/A	N/A	62	45	80	59	Normal	Yes
09:029	hall by rm 113	Heat	1	135	135	0	N/A	N/A	62	45	80	59	Normal	Yes
09:030	rm 113	Photo	1	1.5	122	60	113	120	60	0	61	1	Normal	Yes
09:031	rm 111	Photo	1	1.5	122	60	113	120	60	0	66	9	Normal	Yes
09:032	rm 109	Photo	1	1.5	151	89	113	120	89	0	91	3	Normal	Yes
09:033	food service room	Photo	1	1.5	122	60	113	120	60	0	60	0	Normal	Yes
09:034	area by hood	Heat	1	135	135	0	N/A	N/A	64	47	87	64	Normal	Yes
09:035	rm 131	Photo	1	1.5	143	81	113	120	82	1	84	4	Normal	Yes
09:036	rm 130	Photo	1	1.5	151	89	113	120	90	1	92	4	Normal	Yes
09:037	rm 132	Photo	1	1.5	153	91	113	120	90	0	99	12	Normal	Yes
09:038	hall by rm 132	Photo	1	1.5	122	60	113	120	60	0	66	9	Normal	Yes
09:039	rm 139	Photo	1	1.5	146	84	113	120	85	1	87	4	Normal	Yes
09:040	rm 135	Photo	1	1.5	145	83	113	120	84	1	86	4	Normal	Yes
09:041	hall by 134	Photo	1	1.5	122	60	113	120	60	0	70	16	Normal	Yes
09:042	rm 134	Photo	1	1.5	153	91	113	120	91	0	94	4	Normal	Yes
09:043	rm 136	Photo	1	1.5	150	88	113	120	87	0	91	4	Normal	Yes
09:044	rm 137	Photo	1	1.5	145	83	113	120	83	0	87	6	Normal	Yes
09:045	rm 139	Photo	1	1.5	151	90	113	120	89	0	106	26	Normal	Yes
09:046	hall by rm 138	Photo	1	1.5	122	60	113	120	60	0	66	9	Normal	Yes
09:047	rm 138	Photo	1	1.5	149	87	113	120	87	0	91	6	Normal	Yes
09:048	rm 140	Photo	1	1.5	141	79	113	120	79	0	82	4	Normal	Yes
09:049	rm 141	Photo	1	1.5	145	83	113	120	83	0	86	4	Normal	Yes
09:050	rm 143	Photo	1	1.5	147	85	113	120	85	0	91	9	Normal	Yes
09:051	hall by rm 142	Photo	1	1.5	122	60	113	120	60	0	70	16	Normal	Yes
09:052	rm 142	Photo	1	1.5	150	89	113	120	88	0	92	4	Normal	Yes
09:053	rm 144	Photo	1	1.5	152	90	113	120	90	0	93	4	Normal	Yes
09:054	rm 145	Photo	1	1.5	146	84	113	120	84	0	86	3	Normal	Yes

DETECTOR STATUS

ID	Name	Type	Zn	Sen	ATL	ACA	MT	TT	CAV	CA%	PCA/CO	PA%	Status	NFPA72
09:055	alt nurse station	Heat	1	135	135	0	N/A	N/A	62	45	82	60	Normal	Yes
09:056	alt. above couch	Heat	1	135	135	0	N/A	N/A	62	45	82	60	Normal	Yes
33:001	right side nurse	Photo	1	1.5	140	78	113	120	78	0	82	6	Normal	Yes
33:002	left side nurse	Photo	1	1.5	123	61	113	120	60	0	66	8	Normal	Yes
33:003	nurses station	Photo	1	1.5	122	60	113	120	60	0	61	1	Normal	Yes
33:004	1st fl tv area	Photo	1	1.5	122	61	113	120	60	0	68	11	Normal	Yes
33:005	hall by rm 107	Photo	1	1.5	122	60	113	120	60	0	70	16	Normal	Yes
33:006	hall by rm 101	High-HT	1	150	150	0	N/A	N/A	64	42	78	52	Normal	Yes
33:007	rm 101	Photo	1	1.5	122	60	113	120	60	0	60	0	Normal	Yes
33:008	rm 103	Photo	1	1.5	122	60	113	120	60	0	60	0	Normal	Yes
33:009	rm 105	Photo	1	1.5	122	60	113	120	60	0	61	1	Normal	Yes
33:010	rm 107	Photo	1	1.5	122	60	113	120	60	0	61	1	Normal	Yes
33:011	rm 106	Photo	1	1.5	166	104	113	120	103	0	110	9	Normal	Yes
33:012	rm 104	Photo	1	1.5	122	60	113	120	60	0	61	1	Normal	Yes
33:013	rm 102	Photo	1	1.5	123	60	113	120	60	0	68	12	Normal	Yes
33:014	chapel	Photo	1	1.5	122	60	113	120	60	0	62	3	Normal	Yes
33:015	hall by front	Photo	1	1.5	123	60	113	120	60	0	72	19	Normal	Yes
33:016	court yard dining	Photo	1	1.5	122	60	113	120	60	0	62	3	Normal	Yes
33:017	court yard dining	Photo	1	1.5	122	60	113	120	60	0	61	1	Normal	Yes
33:018	front lobby	Photo	1	1.5	122	60	113	120	60	0	60	0	Normal	Yes
33:019	by rose dining	Photo	1	1.5	122	60	113	120	60	0	68	12	Normal	Yes
33:020	rose dining	Photo	1	1.5	143	81	113	120	81	0	85	6	Normal	Yes
33:021	rose dining	Photo	1	1.5	122	60	113	120	60	0	68	12	Normal	Yes
33:022	hall by big elev.	Photo	4	1.5	122	60	113	120	60	0	74	22	Normal	Yes
33:023	hall by admin bldg.	Photo	1	1.5	123	60	113	120	60	0	68	12	Normal	Yes
33:024	admin area	Photo	1	1.5	123	61	113	120	60	0	68	11	Normal	Yes
33:025	hall by offices	Photo	1	1.5	124	62	113	120	62	0	70	12	Normal	Yes
33:026	storage	Photo	1	1.5	123	60	113	120	60	0	66	9	Normal	Yes
33:027	hall by storage	Photo	1	1.5	156	94	113	120	94	0	98	6	Normal	Yes
33:028	storage supply	Photo	1	1.5	152	90	113	120	90	0	94	6	Normal	Yes
33:029	mech by human res.	Photo	1	1.5	122	60	113	120	60	0	61	1	Normal	Yes
33:030	hall by human res.	Photo	1	1.5	122	60	113	120	60	0	66	9	Normal	Yes
33:031	outside human res.	Photo	1	1.5	122	60	113	120	60	0	66	9	Normal	Yes
33:032	human res.	Photo	1	1.5	123	61	113	120	60	0	72	17	Normal	Yes
33:033	staff lounge	Photo	1	1.5	123	61	113	120	62	1	68	11	Normal	Yes
33:034	offices 1st fl	Photo	1	1.5	122	60	113	120	60	0	70	16	Normal	Yes
33:035	offices 1st fl	Photo	1	1.5	122	60	113	120	60	0	66	9	Normal	Yes
33:036	offices 1st fl	Photo	1	1.5	122	60	113	120	60	0	82	35	Normal	Yes
33:037	hall by admin office	Photo	1	1.5	123	60	113	120	60	0	70	15	Normal	Yes
33:038	hall by elev.	Photo	1	1.5	122	60	113	120	60	0	60	0	Normal	Yes
33:039	hall by activity	Photo	1	1.5	122	60	113	120	60	0	61	1	Normal	Yes
33:040	activity	Photo	1	1.5	123	60	113	120	60	0	68	12	Normal	Yes
33:041	activity	Photo	1	1.5	136	74	113	120	74	0	78	6	Normal	Yes
33:042	phone room	Photo	1	1.5	122	60	113	120	60	0	66	9	Normal	Yes
33:043	mech rm by s. elev.	Photo	1	1.5	122	60	113	120	60	0	68	12	Normal	Yes
33:044	service hallway	Photo	1	1.5	122	60	113	120	60	0	68	12	Normal	Yes
33:045	service hallway	Photo	1	1.5	123	60	113	120	60	0	74	22	Normal	Yes
33:046	back hall by kitchen	Photo	1	1.5	122	60	113	120	60	0	61	1	Normal	Yes
33:047	back hall by kitchen	Photo	1	1.5	124	62	113	120	62	0	106	70	Normal	Yes
33:048	mech rm by generator	Photo	1	1.5	123	60	113	120	62	3	70	15	Normal	Yes
33:049	elec rm by generator	Photo	1	1.5	122	60	113	120	60	0	60	0	Normal	Yes
33:050	elec. rm. in altimer	Photo	1	1.5	122	60	113	120	60	0	61	1	Normal	Yes
33:051	by samll elev. 1st	Photo	7	1.5	122	60	113	120	60	0	72	19	Normal	Yes
33:052	mech rm by tv rm	Photo	1	1.5	122	60	113	120	60	0	66	9	Normal	Yes
33:053	generator rm.	Photo	1	1.5	122	60	113	120	60	0	63	4	Normal	Yes
33:054	medication room 1st	Photo	1	1.5	122	60	113	120	60	0	61	1	Normal	Yes
33:055	enviornmental cart rm	Photo	1	1.5	122	60	113	120	60	0	68	12	Normal	Yes
33:056	enviornmental cart rm	Photo	1	1.5	122	60	113	120	60	0	60	0	Normal	Yes
33:057	1st fl linen closet	Photo	1	1.5	122	60	113	120	60	0	66	9	Normal	Yes
33:058	small kitchen 1st fl	Photo	1	1.5	122	60	113	120	60	0	61	1	Normal	Yes
33:059	kitchen	High-HT	1	150	150	0	N/A	N/A	78	52	96	64	Normal	Yes

DETECTOR STATUS

ID	Name	Type	Zn	Sen	ATL	ACA	MT	TT	CAV	CA%	PCA/CO	PA%	Status	NFPA72
33:060	kitchen	High-HT	1	150	150	0	N/A	N/A	77	51	80	53	Normal	Yes
33:061	above F.A.C.P.	Photo	1	1.5	122	60	113	120	60	0	61	1	Normal	Yes
33:090	TT LOBBY	Photo	1	1.5	163	101	113	120	101	0	104	4	Normal	Yes
33:091	TT LOBBY	Photo	1	1.5	155	92	113	120	92	0	96	6	Normal	Yes
33:092	TT LOBBY	Photo	1	1.5	152	89	113	120	89	0	94	7	Normal	Yes
33:093	TT LOBBY	Photo	1	1.5	122	60	113	120	60	0	62	3	Normal	Yes
33:094	chiller ahu unit	Photo Duct	1	1.1	119	57	113	120	57	0	60	4	Normal	Yes
33:095	ahn #6 1st fl	Photo Duct	1	1.1	117	55	113	120	55	0	59	6	Normal	Yes
33:096	CHAPEL DUCT	Photo	1	1.5	122	60	113	120	60	0	64	6	Normal	Yes
33:097	ahn #5 1st fl	Photo Duct	1	1.1	115	52	113	120	52	0	56	6	Normal	Yes
33:098	kitchen	High-HT	1	150	150	0	N/A	N/A	82	54	96	64	Normal	Yes
33:099	kitchen elev.	High-HT	7	150	150	0	N/A	N/A	0	0	0	0	Normal	Yes